



WPP-Serie
PowerPoint
orientabile



WPPH-Serie
PowerPoint
fisso



VLBS
Anello a staffa saldabile
ribaltabile 180°
(LPW per ancoraggio in daN)



	Numero di braccia	Direzione di tiro	tutte le varianti						tutte le varianti														
			WPP 0,63 t	WPP 1,5 t	WPP 2,5 t	WPP 4 t	WPP 5 t	WPP 8 t	WPPH 0,63 t	WPPH 1,5 t	WPPH 2,5 t	WPPH 4 t	WPPH 5 t	WPPH 8 t	VLBS 1,5 t	VLBS 2,5 t	VLBS 4 t	VLBS 6,7 t	VLBS 10 t	VLBS 16 t	LBS(1) RS 0,5 t	LBS(3) RS 1 t	LBS(5) RS 2 t
	1	0°	0,6	1,5	2,5	4	6,7	10	0,6	1,5	2,5	4	6,7	10	1,5	2,5	4	6,7	10	16	0,5	1	2
	2	0°	1,2	3	5	8	13,4	20	1,2	3	5	8	13,4	20	3	5,0	8	13,4	20	32	1	2	4
	1	90°	0,6	1,5	2,5	4	5	8	0,6	1,5	2,5	4	5	8	1,5	2,5	4	6,7	10	16	0,5	1	2
	2	90°	1,2	3	5	8	10	16	1,2	3	5	8	10	16	3	5,0	8	13,4	20	32	1	2	4
	2	0-45°	0,8	2,1	3,5	5,6	7	11,2	0,8	2,1	3,5	5,6	7	11,2	2,1	3,5	5,6	9,3	14	22,4	0,7	1,4	2,8
	2	45-60°	0,6	1,5	2,5	4	5	8	0,6	1,5	2,5	4	5	8	1,5	2,5	4	6,7	10	16	0,5	1	2
	2	asimetrico	0,6	1,5	2,5	4	5	8	0,6	1,5	2,5	4	5	8	1,5	2,5	4	6,7	10	16	0,5	1	2
	3+4	0-45°	1,3	3,1	5,2	8,4	10,5	16,8	1,3	3,1	5,2	8,4	10,5	16,8	3,15	5,25	8,4	14	21	33,6	1,05	2,1	4,2
	3+4	45-60°	0,9	2,2	3,7	6	7,5	12	0,9	2,2	3,7	6	7,5	12	2,25	3,75	6	10	15	24	0,75	1,5	3
	3+4	asimetrico	0,6	1,5	2,5	4	5	8	0,6	1,5	2,5	4	5	8	1,5	2,5	4	6,7	10	16	0,5	1	2
Sp. Cordone di saldatura →			1 3,5	1 4,5	HY 3+5	HY 3+6	HY 3+8	HY 3+10	1 3,5	1 4,5	HY 3+5	HY 3+6	HY 3+8	HY 3+10	HV 5+3	HV 7+3	HV 8+3	HV 12+4	HV 16+4	HV 25+6	HV 5+3	HV 8+3	HV 12+4

			VRBS-FIX (LRBS-FIX per ancoraggio in daN)							VRBK-FIX Golfare ad anello per spigoli a 90° (LRBK-FIX per anco- raggio in daN)			ABA (L-ABA per ancoraggio in daN)																			
Numero di braccia Direzione di tiro																																
			VRBS-FIX 4 t		VRBS-FIX 6,7 t		VRBS-FIX 10 t		VRBS-FIX 16 t		VRBS-FIX 31,5 t		VRBS 50 t		VRBK-FIX 4 t		VRBK-FIX 6,7 t		VRBK-FIX 10 t		ABA 1,6 t		ABA 3,2 t		ABA 5 t		ABA 10 t		ABA 20 t		ABA 31,5 t	
			8000 daN		13400 daN		20000 daN								8000 daN		13400 daN		20000 daN		3200 daN		6400 daN		10000 daN		20000 daN					
	1	0°	4	6,7	10	16	31,5	50					4	6,7	10				1,6	3,2	5	10			20	31,5						
	2	0°	8	13,4	20	32	63	100					8	13,4	20				3,2	6,4	10	20			40	63						
	1	90°	4	6,7	10	16	31,5	50					4	6,7	10				1,6	3,2	5	10			20	31,5						
	2	90°	8	13,4	20	32	63	100					8	13,4	20				3,2	6,4	10	20			40	63						
	2	0-45°	5,6	9,38	14	22,4	45	70					5,6	9,3	14				2,2	4,5	7,1	14,1			28	45						
	2	45-60°	4	6,7	10	16	31,5	50					4	6,7	10				1,6	3,2	5	10			20	31,5						
	2	asimetrico	4	6,7	10	16	31,5	50					4	6,7	10				1,6	3,2	5	10			20	31,5						
	3+4	0-45°	8,4	14,1	21	33,6	67	105					8,4	14	21				3,4	6,8	10,6	21,2			42	67						
	3+4	45-60°	6	10,1	15	24	47,5	75					6	10	15				2,4	4,8	7,5	15			30	47,5						
	3+4	asimetrico	4	6,7	10	16	31,5	50					4	6,7	10				1,6	3,2	5	10			20	31,5						
Sp. Cordone di saldatura →			HY 3	HY 5	HY 6	HY 9	HY 12	HY 25+8					HY 3+4	HY 3+5	HY 8+3				┐ 4	┐ 6	┐ 7	┐ 8			┐ 12	┐ 15						

